Windows displays the following error when installing Exaquantum software.

The browser error is caused by Hotfix KB890175. The workaround for this problem is to set a registry key to a value of 0 as follows:

[HKEY_LOCAL_MACHINE\SOFTWARE\Microsoft\Internet Explorer\ActiveX Compatibility\{ADB880A6-D8FF-11CF-9377-00AA003B7A11}]"Compatibility Flags"=dword:00000000

This, however, undoes the work of the Hotfix security patch and the key needs to be set back to a value of 1024 (hex) after the browser has run.

(checked 04/10/2017 - RLT)