Knowledge

Base



MSDataShape error when creating Function Block

KB-0062-22

Document Summary		
Article Type	User Guide	
Products Affected	Exaquantum/PIMS	
Versions Affected	R3.30, R3.40	
Function Affected	Exaquantum Tag Editor	
Available Resolution	Apply the latest Windows Updates	
Audience	Administrators, System Integrators and Users	
Summary	Tag Editor unexpectedly errors when creating a Function Block. The error is: Tag Editor Unexpected error Unexpected error occured: ————————————————————————————————————	
Review Date	Document to be reviewed before November 2024	



Table of Contents

Table of Contents	1
Chapter 1 Introduction	2
Chapter 1 Introduction 1.1 Audience Chapter 2 Issue 2.1 Issue Description 2.2 Root Cause Chapter 3 Issue Resolution 3.1 Resolution steps Chapter 4 Further Reading Copyright and Trademark Notices	3
1.1 Audience	
3.1 Resolution steps	4
Chapter 1 Introduction 1.1 Audience	5
Copyright and Trademark Notices	6
Highlights	7

Chapter 1 Introduction

This document will detail the Exaquantum issue and the underlying root cause. There is then further detail on resolving the issue.


1.1 Audience

This guide is intended for users who are affected by the issue as well as system integrators and administrators trying to resolve the issue.

Chapter 2 Issue

2.1 Issue Description

When attempting to create a Function Block manually using the Tag Editor, an ADO MSDataShape error is displayed:



The issue can occur on either the Exaquantum Server or the Exaquantum Client.

2.2 Root Cause

The Windows 1809 code base introduced a change in the MSDataShape Provider (MSADDS) that causes this error.

The affected Windows versions are:

Windows 10, version 1809, all editions;

Windows Server 2019, all editions.

Currently supported versions of Exaquantum that support these operating systems are:

Exaquantum/PIMS R3.30

Exaquantum/PIMS R3.40

Chapter 3 Issue Resolution

3.1 Resolution steps

Install the latest Windows Updates. The fix is offered as part of a cumulative update for Windows.

The fix is incorporated into MSVCRT.DLL and is confirmed to be included in KB4495667. This KB will be superseded as per the Microsoft cumulative update cycle.

Chapter 4 Further Reading

For further information please visit the <u>Yokogawa Marex support website</u> or contact YMX at the <u>support.ymx@yokogawa.com</u> email address.

Copyright and Trademark Notices

© 2022 Yokogawa Electric Corporation

All Rights Reserved

The copyright of the programs and online manuals contained in the software medium of the Software Product shall remain with YOKOGAWA.

You are allowed to print the required pages of the online manuals for the purposes of using or operating the Product; however, reprinting or reproducing the entire document is strictly prohibited by the Copyright Law.

Except as stated above, no part of the online manuals may be reproduced, transferred, sold, or distributed to a third party in any manner (either in electronic or written form including, without limitation, in the forms of paper documents, electronic media, and transmission via the network).

Nor it may be registered or recorded in the media such as films without permission.

Trademark Acknowledgements

- CENTUM, ProSafe, Exaquantum, Vnet/IP, PRM, Exaopc, Exaplog, Exapilot,
 Exasmoc and Exarge are registered trademarks of Yokogawa Electric Corporation.
- Microsoft, Windows, Windows Server, SQL Server, Excel, Internet Explorer, SharePoint, ActiveX, Visual Basic, Visual C++, and Visual Studio are either registered trademarks or trademarks of Microsoft Corporation in the United States and other countries.
- Adobe and Acrobat are registered trademarks of Adobe Systems Incorporated and registered within particular jurisdictions.
- Ethernet is a registered trademark of XEROX Corporation.
- All other company and product names mentioned in this manual are trademarks or registered trademarks of their respective companies.
- We do not use TM or ® mark to indicate those trademarks or registered trademarks in this manual.
- We do not use logos in this manual.

Highlights

The Highlights section gives details of the changes made since the previous issue of this document.

Summary of Changes

This is Issue 2.0 of the document related to Product Library version 2.0.

Detail of Changes

The changes are as follows:

Chapter/Section/Page	Change
Front page	Review Date updated
Page 5	Email address updated